

**DEPARTMENT OF TRANSPORTATION****DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: xx.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-026012**Date Inspected:** 27-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China**CWI Name:** Mr. Liu Huajie**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG Trial Assembly**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance (QA) Inspector Raghavendra Reddy was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This QA Inspector observed the following work in progress:

BLAST SHOP 1.

Visual Inspection after Blast at OBG Segment 14 East.

This Quality Assurance (QA) Inspector performed random visual inspection of OBG Segment 14 East Internal side, side panel and edge panel surfaces after grit blasting. Areas that marked for repair were recorded for future repair. Areas requiring additional grinding were marked by QA and repaired by ZPMC personnel. For more information see below attached picture.

Location 1

In between PP127 and PP127.5 a base metal repair was visibly observed on the bottom Plate one (01) location and side plate two (02) location and one location stiffener cut area of EB3053A, base metal repair approx 1Meter. On cross beam side of segment, Areas were marked.

---

# WELDING INSPECTION REPORT


( Continued Page 2 of 2 )

---

## Location 2

In between PP128 and PP128.3 on cross beam side of segment, base metal repair was visibly observed on the Side Plate I ribs and connection plates, and need to grind temporary attachment area. Areas were marked.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.



## Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

## Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (15000422372), who represents the Office of Structural Materials for your project.

---

**Inspected By:** Tharikoppada,Reddy

Quality Assurance Inspector

---

**Reviewed By:** Miller,Mark

QA Reviewer